



SUBJECT : OMNISTAR FIRMWARE UPGRADE
APPLICATION : 3000 SERIES
DESCRIPTION : IDENTIFYING THE FIRMWARE VERSION
PROCEDURE : 3000 - 3100

OmniSTAR requires your firmware on your GPS receiver to be upgraded, in order to maintain a high standard of service from your GPS receiver. (Please note this procedure is different from the Frequency Changeover to OCSAT).

These are the procedures to follow for checking your firmware on the 3000 and 3100 receivers with LCD displays.



Turn the unit on and allow it to finish its initialisation sequence.


Use the **DOWN** button to move through the Main Menu items until the **ABOUT MENU** appears.

The **ABOUT** menu repeats the firmware version and unit serial number as shown during the start-up sequence.

Use the **RIGHT ARROW** button to move through the **ABOUT** menu until the firmware version screen appears.

Main Software Version

shows the Main Software version installed into the receiver and its issue date.



The software version needs to be 04.01.01 or above.

Please contact OmniSTAR on 1300 794 498 if you have any problems between business hours.