

SUBJECT : OmniSTAR FIRMWARE UPGRADE
APPLICATION : OmniSTAR OUTBACKS
DESCRIPTION : IDENTIFYING THE FIRMWARE VERSION
PROCEDURE : OUTBACKS

OmniSTAR requires your firmware on your GPS receiver to be upgraded, in order to maintain a high standard of service from your GPS receiver. (Please note this procedure is different from the Frequency Changeover to OCSAT).



1. Menu Button.

2. Down Arrow.

3. Enter Button.



From power up:

1. Press the **MENU** button.
2. Press the **DOWN** arrow until the > points to the **DIAGNOSTICS** title.
3. Press **ENTER**.
4. Press the **DOWN** arrow until the **GPS SOFTWARE** screen appears.
5. Below this will be the **VER** number. Version 4.8 is the current required version.

Please contact OmniSTAR on 1300 794 498 if you have any problems between business hours.