

GPS Receiver	VBS Subscription	HP/XP Subscription	Firmware Version
Novatel Pro Pak LB OmniSTAR 8300 Sokkia 2650 LB	RSOCVBS	RSOCHP	Main: 2.312 DSP: 1.102 or 1.004b5 XLINIX: 1.03
Novatel Pro Pak V3 OmniSTAR 8305 Novatel V1 / V3	RSOCVBS	RSOCHP	Version: 3.1000s15
Beeline B3/1 Beeline Arro	RSOC	RSOCHP (no XP) HP Upgrade	Main: Unknown DSP: 1.102 or 1.004b5 XLINIX: 1.03
Topcon GS200 Topcon MAP-HP OmniSTAR 8400	RSOCVBS	RSOCHP Note: enable all link vectors	Release:1.3 (em_bulb board firmware)
Trimble AgGPS 252 / 332 / DSM 232 OmniSTAR 8200	RSOCVBS	RSOCHP	Release 3.1 / 3.5 (the same)
Trimble AgGPS114/132 OmniLite 132 OmniSTAR 3200	RSOCVBS	n/a	3.00 or 1.52 special
Trimble ProXRS	RSOCVBS	n/a	3.00 (TBC-correspondence Max Huff/Hans Visser)
OmniSTAR Mk II	n/a	n/a	Receiver Superseded
OmniSTAR 3000	RSOCVBS		> Version 4
OmniSTAR 3500/3510	RSOCVBS	n/a	> 2.0
Landstar/Leica (Mk IV)	RSOCVBS Note: expiry date & link vector only	n/a	
Hemisphere	RSOCVBS	n/a	OmniSTAR application: 4.8
CSI/Satloc SLXg	RSOCVBS	n/a	OmniSTAR application: 4.8
CSI/Satloc SLXg3	RSOCVBS	n/a	OmniSTAR application: 4.8
KEE Triple X	RSOCVBS	n/a	OmniSTAR application: 4.8
CSI DGPSMax/SLXg3	RSOCVBS	n/a	OmniSTAR application: 4.8