


**SUBJECT** : OmniSTAR FIRMWARE UPGRADE  
**APPLICATION** : OmniSTAR TRIMBLE AG132 & 332  
**DESCRIPTION** : IDENTIFYING THE FIRMWARE VERSION  
**PROCEDURE** : TRIMBLE AG 132 & TRIMBLE AG 332

OmniSTAR requires your firmware on your GPS receiver to be upgraded, in order to maintain a high standard of service from your GPS receiver. (Please note this procedure is different from the Frequency Changeover to OCSAT).

Both the Trimble AgGPS 132 and the AgGPS 332 display their firmware version in the same menu screen.


From the home screen.




Press the RIGHT arrow  until the STATUS screen appears.




Press the DOWN  arrow ONCE.



Press the RIGHT arrow  until the RECEIVER STATUS screen appears.



Press the DOWN button  until the VERSION screen appears.



Version 3.00 or above is suitable firmware.

**Please contact OmniSTAR on 1300 794 498 if you have any problems between business hours.**